

CLEAR AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

Airport Information:

- Location: Approximately 2 miles west of the Parks Highway between Healy and Nenana. Turn west on Clear Road and north on Anderson Road. It is on the right.
- District: Interior
- Airport Manager: Bill O'Halloran
- District Maintenance Manager: Ron Reitano
- Pavement Surface: Asphalt Concrete
- Last Pavement Construction: 1997
- Pavement layout: Runway 01-19, three taxiways and two aprons
- Design Aircraft: Twin Otter
- 2000 Enplanements: no data
- Airport Class: Non-Primary
- Last pavement condition survey: 2002
- Next planned pavement condition survey: 2005
- 2001 reported pavement maintenance and/or changed conditions: No reports
- Recommendations: See PCI maps